

Design Advisory - USB Audio 2.0 Stereo Driver PID

IN THIS DOCUMENT

- ▶ Symptoms
 - ▶ Problem
 - ▶ Solution
-

1 Symptoms

If you install the USB Audio 2.0 Stereo Driver for Windows (XMOS) in parallel with the Theysycon USB Audio Class 2.0 Windows Evaluation/Production driver, the second installation will break the first installation. Uninstalling the second driver does not repair the first driver.

2 Problem

The problem is caused by both drivers using the same PID.

3 Solution

Uninstall both packages, and then install the driver you want to use.